

APPLICATION & REMOVAL OF WARNING FLAG 1059 WITH RED AG TOOL 1024



PULL ON THE RINGS
UNTIL THE CLAMP STAYS OPEN.
ATTACH TOOL TO A HOTSTICK


1



2

3

PUT THE CLAMP RING OVER THE PEG ON
LEFT CUP OF TOOL. 2
SWING THE SPRING LOADED RIGHT CUP
TO THE LEFT & PUT CLAMP INTO CUP.
RELEASE CUP SO CLAMP IS HELD IN
TOOL. 3



SHOWS RINGS HOOKED OVER
PEG

3

4



POSITION THE CLAMP UP
UNDERNEATH THE CONDUCTOR
AND PUSH UP QUICKLY
CAUSING IT TO SNAP SHUT



TO REMOVE PUT HOOK
THRU ONE OF THE FINGER
RINGS ON SNAP CLAMP AND
PULL DOWN UNTIL IT OPENS
THEN LIFT UP TO IT SLIDES
ONTO THE HOOK TOOL OR
FALLS TO THE GROUND

HOTSTICK